

85490 page 1

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved
OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

Required under USDL Safety and Health Regulations for Ship Repairing,
Shipbuilding, and Shipbreaking (29 CFR 1915, 1916, 1917)

"SPS"		EMERGENCY TELEPHONE NO.	
MANUFACTURER Seattle Pottery Supply Inc.			
ADDRESS (Nun) 35 So. HANFORD SEATTLE, WA 98134 (206) 587-0570			
CHEMICAL NAME AND SYNONYMS		TRADE NAME AND SYNONYMS WET/DRY POTTERY CLAY	
CHEMICAL FAMILY CLAY	FORMULA	CASTING BODY / THROWING	

SECTION II - HAZARDOUS INGREDIENTS						
PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)	
PIGMENTS	N/A		BASE METAL	N/A		
CATALYST	N/A		ALLOYS	N/A		
VEHICLE	N/A		METALLIC COATINGS	N/A		
SOLVENTS	N/A		FILLER METAL PLUS COATING OR CORE FLUX			
ADDITIVES	N/A		OTHERS			
OTHERS						
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES					%	TLV (Units)

SECTION III - PHYSICAL DATA			
BOILING POINT (°F.)	N/A	SPECIFIC GRAVITY (M ₂ O-1)	2.65 - 2.8
VAPOR PRESSURE (mm Hg.)	N/A	PERCENT VOLATILE BY VOLUME (%)	
VAPOR DENSITY (AIR-1)	N/A	EVAPORATION RATE (_____ #)	
SOLUBILITY IN WATER	N/A		
APPEARANCE AND ODOR	N/A		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA					
FLASH POINT (Method used)	N/A	FLAMMABLE LIMITS	<table border="1"> <tr> <td>Low</td> <td>High</td> </tr> </table>	Low	High
Low	High				
EXTINGUISHING MEDIA	N/A				
SPECIAL FIRE FIGHTING PROCEDURES	NONE				
UNUSUAL FIRE AND EXPLOSION HAZARDS	NONE				

85490 Casting Body / 1H20W + NG, PAPER CLAY

85490 Page 2

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE 10MG./M 3 AS CLAY DUST

EFFECTS OF OVEREXPOSURE
NOT ESTABLISHED

EMERGENCY AND FIRST AID PROCEDURES

INHALATION - REMOVE TO FRESH AIR (AVOID BREATHING DUST)

SKIN CONTACT - WASH WITH WATER

EYE CONTACT - FLUSH WITH PLENTY OF WATER

SECTION VI - REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	XXX	NONE

INCOMPATIBILITY (Materials to avoid)

HAZARDOUS DECOMPOSITION PRODUCTS

HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	XXX	NONE

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
HANDLE AS NORMAL SOLID WASTE, SCOOP UP AND PLACE IN APPROPRIATE MARKED
CONTAINERS. WEAR OSHA APPROVED RESPIRATOR MASK FOR PROTECTION

WASTE DISPOSAL METHOD
WASTE MATERIAL MAY BE DISPOSED OF UNDER CONDITIONS
WHICH MEET FEDERAL, STATE AND LOCAL ENVIRONMENTAL CONTROL REGULATIONS

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type) OSHA APPROVED DUST RESPIRATOR IS RECOMMENDED

VENTILATION	LOCAL EXHAUST	SPECIAL LEVEL OTHER
	MECHANICAL (General)	

PROTECTIVE GLOVES	NONE	EYE PROTECTION	NORMAL PROTECTION
-------------------	------	----------------	-------------------

OTHER PROTECTIVE EQUIPMENT

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

NORMAL PRECAUTION FOR NUISANCE DUST SHOULD BE PROVIDED

OTHER PRECAUTIONS